PSpice Schematic Color Editing

Editing the Graph

- Select **Tools** from the top menu
  - o Select **Options** from the Tool menu
    - ▪ Go to **Color Settings**
      - Here you can change the background to white, and the foreground (gridlines) to black.

Editing the Trace

- Select **Tools** from the top menu
  - o Select **Options** from the Tool menu
    - ▪ Go to **Color Settings**
      - Add black from the **Available Colors** to the **Trace Color**.
- Right click on the trace labels. These will be in the bottom left of the graph.
  - o Select **Trace Properties**.
    - ▪ Select black as the trace color.
    - ▪ You can also set the pattern, thicken, and symbol for the variable you are plotting.